

Andy Tiernan Classics

1/08/2009

The Old Railway Station Framlingham Suffolk IP13 9EE Tel 01728 724321 Fax 01728 723767

Vintage/Classic Used Motorcycle Pre MOT Type Cursory Evaluation Report			Dated 8/03/2010		Tester Paul				
Make BSA		Model Blue Star		Year 1932		Reg No 756XUA		Oils checked E G P	
Price £5,500.00			Colour Black			Stock No 4790bsa		cc350	
VIN/Frame No Z5 401				Location N/S top down tube			Engine No Z5 137		
Documents: V5C ✓		Old Logbook Buff Green		Tax expiry 30/04/2010			MOT expiry		
History From a Northern Irish collection , with his advancing years the owner decided to have a thin out									

		Nice	Mean	Poor	COMMENTS				
E L E C T R I C S	Headlamp Operation	√							
	Rear lamp Operation	√							
	Stop lamp Operation	n/a							
	Rear reflector	√							
	Horn Operation	√							
	Charging System Operation	√			Electronic				
	Battery	√			Voltage = 6v				
S T E E P I N G S I O N	Head Bearings	√							
	Forks	√							
	Swing Arm Bearings	n/a							
	Wheel Alignment	√							
	Girder Links If Applicable	√							
B R A K E S	Front Brake	√							
	Rear Brake	√							
	Controls Clevis Pins etc	√							
W T H E R E S	Front Tyre tread depth	√			Size 3.25x19		(see ROSPA note below) Avon s/master		
	Rear Tyre tread depth	√			Size 3.25x19		(see ROSPA note below) Avon SM		
	Front Bearings	√							
	Rear Bearings	√							
	Front Rim	√			Plating = n/a		painted		
	Rear Rim	√			Plating = n/a		painted		
	Front Spokes	√							
	Rear Spokes	√							
G E N E R A L	Exhaust Silencers	√			Plating = Good				
	Exhaust Pipes	√			Plating = Good				
	Fuel System Leaks	√							
	Speedo	n/a			Reading = n/a				
	Cables	√							
	Handle bars/Lever	√			Plating = Good				
	Final Drive Chain	√							
	Rear Sprocket		√		Little worn				
	Condition of Frame	√							
	Engine Condition	√			Starting = Easy				
	Oil Leaks	√							
	Gearbox operation	√			No of gears 4				
	Clutch operation	√							
	Road Test Evaluation	√			Distance covered		Miles Yard Test		
	Carburettor	√			Type =				
Petrol Tank	√			Plating = n/a		Paint = Silver			

Blue Stars don't turn up so often now so have one to enjoy

This report is only the opinion of the tester on the day and should only be considered as a rough guide as time does not permit an in depth report. Machines of this age will always require ongoing work. We strongly recommend that all machines be recommissioned before any long term use due to the length of time that they may have been stored. WWW.ROSPA.com recommend tyres that have been in storage for over 6 years or in use for 10 years should be replaced. The speedo reading is not necessarily an indication of the true mileage.